

WEST VIRGINIA



NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION


Date: 4/28/17

Operator Project No: 053-16

Pesticides & Asbestos Programs
and Enforcement Branch (SL662)
EPA Region III
OFFICE USE ONLY

Date Rec'd: Check No:
Postmark Date: Paid By:
Notification No: Amount: \$

Type of Notification: Original <input type="checkbox"/> Revision <input checked="" type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>		
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>		
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906		
Facility Description: Name: Vacant Structures - Please see attached for Group 11 (Greenbrier) Address: City: Location Within Facility: County: Number of Floors: Age (Yrs): Building Size (Sq. Ft.): Prior Use: Present Use:		
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002453 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070		
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070		
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Please see attached. WV License #: Please see attached. Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Chris Ciappina WV License #: AD003839 Air Monitor: WV License #:		
Schedule: Asbestos Removal: Start Date: 03/28/17 Completion Date: 06/01/17 Demo/Renovation: Start Date: 03/28/17 Completion Date: 06/01/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)		

Emergency Renovation: Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.									
Demolition Ordered by Government Agency: Agency: _____ Name: _____ Title: _____ Date of Order: ___/___/___ Date Order to Begin: ___/___/___ (Copy of order must be attached.)									
Types of ACM: <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%; vertical-align: top;"> Asbestos Containing Material To Be Removed: Type(s): Please see attached. Pipes: Ln. Ft: % Asbestos: Area: Sq. Ft: % Asbestos: Other: Cu. Ft: % Asbestos: </td> <td style="width: 50%; vertical-align: top;"> Cat. I & II Nonfriable ACM Not To Be Removed: Type(s): Pipes: Ln. Ft: % Asbestos: Area: Sq. Ft: % Asbestos: Other: Cu. Ft: % Asbestos: </td> </tr> </table>		Asbestos Containing Material To Be Removed: Type(s): Please see attached. Pipes: Ln. Ft: % Asbestos: Area: Sq. Ft: % Asbestos: Other: Cu. Ft: % Asbestos:	Cat. I & II Nonfriable ACM Not To Be Removed: Type(s): Pipes: Ln. Ft: % Asbestos: Area: Sq. Ft: % Asbestos: Other: Cu. Ft: % Asbestos:						
Asbestos Containing Material To Be Removed: Type(s): Please see attached. Pipes: Ln. Ft: % Asbestos: Area: Sq. Ft: % Asbestos: Other: Cu. Ft: % Asbestos:	Cat. I & II Nonfriable ACM Not To Be Removed: Type(s): Pipes: Ln. Ft: % Asbestos: Area: Sq. Ft: % Asbestos: Other: Cu. Ft: % Asbestos:								
Description of planned demolition or renovation work and method(s) to be used: Wet methods for demolition and regulated site.									
Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M): Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.									
Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder: STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.									
Waste Transporter: <table style="width: 100%;"> <tr> <td style="width: 50%;">Name: Reclaim Company, LLC</td> <td style="width: 50%;">ID #: WV042918 / WH13715</td> </tr> <tr> <td>Address: P.O. Box 2162</td> <td></td> </tr> <tr> <td>City: Fairmont</td> <td>State: WV Zip Code: 26555</td> </tr> <tr> <td>Contact Person: Steve Gabbert</td> <td>Phone: 304-366-7070</td> </tr> </table>		Name: Reclaim Company, LLC	ID #: WV042918 / WH13715	Address: P.O. Box 2162		City: Fairmont	State: WV Zip Code: 26555	Contact Person: Steve Gabbert	Phone: 304-366-7070
Name: Reclaim Company, LLC	ID #: WV042918 / WH13715								
Address: P.O. Box 2162									
City: Fairmont	State: WV Zip Code: 26555								
Contact Person: Steve Gabbert	Phone: 304-366-7070								
Waste Disposal Site: <table style="width: 100%;"> <tr> <td style="width: 50%;">Name: Meadowfill Landfill</td> <td style="width: 50%;">ID #: SMF-1032</td> </tr> <tr> <td>Address: Rt. 2 Box 68</td> <td></td> </tr> <tr> <td>City: Bridgeport</td> <td>State: WV Zip Code: 26330</td> </tr> <tr> <td>Contact Person: Kelli Sekela</td> <td>Phone: 304-842-2784</td> </tr> </table>		Name: Meadowfill Landfill	ID #: SMF-1032	Address: Rt. 2 Box 68		City: Bridgeport	State: WV Zip Code: 26330	Contact Person: Kelli Sekela	Phone: 304-842-2784
Name: Meadowfill Landfill	ID #: SMF-1032								
Address: Rt. 2 Box 68									
City: Bridgeport	State: WV Zip Code: 26330								
Contact Person: Kelli Sekela	Phone: 304-842-2784								
Certification: I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.									
Signature of Owner/Operator: <u></u> Date: <u>04</u> <u>28</u> <u>17</u>									
Name and Title (Print or Type): <u>Angela Mitchell, Contract Administrator</u>									



**WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 11**

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSLTILE	INSPECTION DATE	INSPECTOR	ANALYST
G-100	100 2ND STREET, RAINELLE	37.971121, -80.767551	Black Ceiling Mastic	30 LF	10%	3/20/2017	K. Tuckwiller AI008994	Sarah Talley
G-101	120 HUGHART ST., RAINELLE	37.969399, -80.767522	Black Mastic on roof by flashing	10 SF	Assumed	3/20/2017	K. Tuckwiller AI008994	Mikaela Batta
			Gray Window Glazing	150 LF	2%			
G-125	163 CENTER ST., RAINELLE	37.970208, -80.767124	Silver Roof Cement/Mastic (above porches)	10 SF	Assumed	3/20/2017	K. Tuckwiller AI008994	Shilpa Ladekar
			Green/White Window Glazing	100 LF	2%			
			Green Floor Tile	8 SF	7%			
G-130	344 9TH STREET, RAINELLE	37.971095, -80.760478	Mastic around chimney	3 SF	Assumed	3/20/2017	K. Tuckwiller AI008994	Ritika Seal
G-235	438 6TH STREET, RAINELLE	37.969103, -80.761707	Black Roof Mastic	10 SF	Assumed	3/20/2017	K. Tuckwiller AI008994	Megan Rumble
G-236	442 6TH STREET, RAINELLE	37.968953, -80.761766	Silver Roof Cement	800 SF	5%	3/20/2017	K. Tuckwiller AI008994	Megan Rumble
			Mastic around roof vent	5 SF	Assumed			
G-237	453 6TH STREET, RAINELLE	37.969198, -80.761157	Silver Roof Cement	800 SF	5%	3/20/2017	K. Tuckwiller AI008994	Ritika Seal
			Mastic around roof vents	5 SF	Assumed			
G-240	112 BRIAR PARK LANE, RAINELLE	37.969150, -80.760794	Black Mastic between porch roof & trailer	5 LF	Assumed	3/20/2017	K. Tuckwiller AI008994	Shilpa Ladekar
			Silver Roof Cement (Bldg 1)	200 SF	Assumed			
G-241	118 BRIAR PARK LANE, RAINELLE	37.969083, -80.760888	Silver Roof Cement	800 SF	3%	3/20/2017	K. Tuckwiller AI008994	Ritika Seal
G-242	159 BRIAR PARK LANE, RAINELLE	37.968525, -80.761188	Mastic around roof vents	5 SF	Assumed	3/20/2017	K. Tuckwiller AI008994	Ritika Seal
G-243	184 11TH STREET, RAINELLE	37.972122, -80.760580	Silver Roof Cement	800 SF	Assumed	3/20/2017	K. Tuckwiller AI008994	Shilpa Ladekar
G-67	343 MAIN STREET, RAINELLE	37.97029, -80.76444	Window Glazing	5 LF	Assumed	3/20/2017	K. Tuckwiller AI008994	N/A
G-82	247 7TH STREET, RAINELLE	37.972185, -80.76318	Mastic on roof of older section	10 SF	Assumed	3/28/2017	K. Tuckwiller AI008994	Mikaela Batta
			Pink/White Window Glazing	20 LF	2%			
G-135	128 11TH STREET, RAINELLE	37.972818, -80.761168	Mastic on roof vents	5 SF	Assumed	3/28/2017	K. Tuckwiller AI008994	Saithya Painkal
			Gray Window Glazing	30 LF	2%			
G-136	129 12TH STREET, RAINELLE	37.974277, -80.760227	Mastic around chimney	2 SF	Assumed	3/28/2017	K. Tuckwiller AI008994	Sarah Talley
G-139	171 3RD STREET, RAINELLE	37.970409, -80.765442	Transite Siding	500 SF	Assumed	3/29/2017	K. Tuckwiller AI008994	Mikaela Batta
			Mastic/Floor Tile	20 SF	Assumed			
G-147	511 JAMES RIVER-KANAWHA TURNPIKE, RAINELLE	37.968057, -80.761001	Mastic/Roof Cement under metal roofing	15 SF	Assumed	3/29/2017	K. Tuckwiller AI008994	Megan Fisher
			Roof Shingles/Mastic (Bldg 1)	200 SF	Assumed			
G-166	264 7TH STREET, RAINELLE	37.971826, -80.763183	Roof Shingles/Cement (Bldg 2)	150 SF	Assumed	3/29/2017	K. Tuckwiller AI008994	Saithya Painkal
G-172	131 4TH STREET, RAINELLE	37.970948, -80.764911	Mastic on Roof Flashing	15 SF	Assumed	3/28/2017	K. Tuckwiller AI008994	N/A
G-173	591 CENTER STREET, RAINELLE	37.973725, -80.760647	NO SUSPECT MATERIALS	N/A	N/A	3/28/2017	K. Tuckwiller AI008994	Saithya Painkal
			Mastic around chimney	3 SF	Assumed			
G-174	LOT 7, WILLOWWOOD TRAILER PARK, RAINELLE	37.965501, -80.771506	Roof Shingles (Bldg 1)	15 SF	Assumed	3/29/2017	K. Tuckwiller AI008994	Megan Fisher
			Silver Roof Cement/Mastic	700 SF	2%			
G-176	214 LOCUST STREET, RAINELLE	37.969802, -80.772938	Mastic on Roof	5 SF	Assumed	3/29/2017	K. Tuckwiller AI008994	Megan Fisher
			Mastic around chimney	5 SF	Assumed			
G-201	187 CROSIER ROAD, RAINELLE	37.986990, -80.750208	Roof Shingles (Bldg 1)	200 SF	Assumed	3/29/2017	K. Tuckwiller AI008994	Saithya Painkal
G-209	405 6TH STREET, RAINELLE	37.969667, -80.761788	Mastic on Roof (Black)	40 SF	Assumed	3/29/2017	K. Tuckwiller AI008994	N/A
G-210	416 (TRAILER 22) 7TH STREET, RAINELLE	37.968679, -80.761106	NO SUSPECT MATERIALS	N/A	N/A	3/29/2017	K. Tuckwiller AI008994	Shilpa Ladekar
			Silver Roof Cement	700 SF	3%			
G-221	10 WILLOWWOOD TRAILER PARK, RAINELLE	37.965778, -80.771583	Black Mastic (siding/roof)	15 SF	Assumed	3/29/2017	K. Tuckwiller AI008994	Megan Fisher
G-247	307 3RD STREET, RAINELLE	37.969079, -80.764206	Mastic around roof vents	3 SF	Assumed	3/29/2017	K. Tuckwiller AI008994	Saithya Painkal
			Mastic on Roof	20 SF	Assumed			
G-105	177 QUINWOOD NUTTERVILLE RD., RUSSELVILLE	38.078193, -80.890396	Mastic around chimney (main)	3 SF	Assumed	3/31/2017	K. Tuckwiller AI008994	Mikaela Batta
			Roof Shingles (Bldg 1)	80 SF	Assumed			
G-265	645 MAIN STREET, RAINELLE	37.973123, -80.760047	Roof Shingles (Bldg 2)	120 SF	Assumed	4/4/2017	K. Tuckwiller AI008994	N/A
G-267	438 KANAWHA AVENUE, RAINELLE	37.967422, -80.783869	NO SUSPECT MATERIALS	N/A	N/A	4/4/2017	K. Tuckwiller AI008994	N/A
G-272	174 BRIAR PARK LANE, RAINELLE	37.968620, -80.761817	Silver Roof Cement	600 SF	3%	4/4/2017	K. Tuckwiller AI008994	Mikaela Batta
			Black Mastic on siding	15 SF	Assumed			
G-273	197 GREENBRIER AVENUE, RAINELLE	37.969827, -80.762961	Mastic Around Roof Vents	20 SF	Assumed	4/4/2017	K. Tuckwiller AI008994	Shilpa Ladekar
G-277	LOT 4, WILLOWWOOD TRAILER PARK, RAINELLE	37.965619, -80.770725	Floor Tile / Mastic	22 SF	Assumed	4/4/2017	K. Tuckwiller AI008994	N/A
G-278	LOT 9, WILLOWWOOD TRAILER PARK, RAINELLE	37.965689, -80.771543	Mastic around vents	5 SF	Assumed	4/4/2017	K. Tuckwiller AI008994	Megan Rumble
G-177	223 7TH STREET, RAINELLE	37.972441, -80.763458	Beige Floor Tile	10 SF	3%	4/13/2017	K. Tuckwiller AI008994	Candace Burrus
			Black Mastic	10 SF	5%			
G-280	448 LOT 19 - 6TH ST. (REED TRAILER PARK), RAINELLE	37.968887, -80.761673	Transite Siding	9200 SF	Assumed	4/24/2017	K. Tuckwiller AI008994	Samantha Card
			Silver Roof Cement	800 SF	3%			
G-290	425 6TH STREET, RAINELLE	37.969438, -80.761582	Gray/Green Linoleum #2	15 SF	25%	4/24/2017	K. Tuckwiller AI008994	N/A
			Mastic around roof vents	5 SF	Assumed			
			Old Wiring (TSI)	30 LF	Assumed	4/24/2017	K. Tuckwiller AI008994	N/A

WEST VIRGINIA


 RECEIVED
 MAY 05 2017

 Pesticides & Asbestos Programs
 and Enforcement Branch (3LC62)

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 4/28/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd:

Check No:

Postmark Date:

Paid By:

Notification No:

Amount: \$

Type of Notification:

Original ☐Revision ☒ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 18 (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

WV License #: AI008690

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 04/12/17

Completion Date: 06/01/17

Demo/Renovation:

Start Date: 04/12/17

Completion Date: 06/01/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Title:

Date of Order: ___/___/___

Date Order to Begin: ___/___/___

(Copy of order must be attached.)

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator:

Date: 04 / 28 / 17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 18

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTOLE	INSPECTOR	INSPECTION DATE	ANALYST	COMPLETE
K-152	358 Youngstown Dr., Clendenin	38.473428, -81.387324	None Detected	N/A	N/A	J. Frazier AI008690	3/20/2017	Sarah Talley	
K-177	1222 Left Fork Leatherwood Rd., Clendenin	38.4691221, -81.356815	Silver Roof Paint	800 SF	5%	J. Frazier AI008690	3/20/2017	Sarah Talley	
K-203	422 Leatherwood Rd., Clendenin	38.459090, -81.361057	Black Tar (porch roof)	300 SF	2%	J. Frazier AI008690	4/21/2017	Ritika Seal	
			Roof Vent Mastic	5 LF	Assumed				

WEST VIRGINIA



RECEIVED
MAY 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (3LC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION


Date: 4/28/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: Check No:
Postmark Date: Paid By:
Notification No: Amount: \$

Type of Notification: Original <input type="checkbox"/> Revision <input checked="" type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Group 19 (Kanawha County) Address: City: County: Location Within Facility: Building Size (Sq. Ft.): Number of Floors: Age (Yrs): Present Use: Prior Use:	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002453 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Jason Frazier WV License #: AI008690 Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Chris Ciappina WV License #: AD003839 Air Monitor: WV License #:	
Schedule: Asbestos Removal: Start Date: 04/12/17 Completion Date: 06/01/17 Demo/Renovation: Start Date: 04/12/17 Completion Date: 06/01/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation: Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.	
Demolition Ordered by Government Agency: Agency: _____ Title: _____ Name: _____ Date Order to Begin: ___/___/___ Date of Order: ___/___/___ (Copy of order must be attached.)	
Types of ACM:	
Asbestos Containing Material To Be Removed: _____ Type(s): Please see attached. Pipes: Ln. Ft: % Asbestos: Area: Sq. Ft: % Asbestos: Other: Cu. Ft: % Asbestos:	Cat. I & II Nonfriable ACM Not To Be Removed: _____ Type(s): _____ Pipes: Ln. Ft: % Asbestos: Area: Sq. Ft: % Asbestos: Other: Cu. Ft: % Asbestos:
Description of planned demolition or renovation work and method(s) to be used: Wet methods for demolition and regulated site.	
Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M): Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.	
Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder: STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.	
Waste Transporter: Name: Reclaim Company, LLC ID #: WV042918 / WH13715 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Waste Disposal Site: Name: Meadowfill Landfill ID #: SMF-1032 Address: Rt. 2 Box 68 City: Bridgeport State: WV Zip Code: 26330 Contact Person: Kelli Sekela Phone: 304-842-2784	
Certification: I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct. Signature of Owner/Operator: <u></u> Date: <u>04</u> / <u>28</u> / <u>17</u> Name and Title (Print or Type): <u>Angela Mitchell, Contract Administrator</u>	



RECLAIM

WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 19

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTILE	INSPECTOR	INSPECTION DATE	ANALYST	COMPLETE
K-147	406 Kanawha Ave., Clendenin	38.489652, -81.340114	Linoleum (bath)	25 SF	Assumed	J. Frazier AI008690	3/20/2017	Sarah Talley	
K-159	744 Maywood Ave., Clenenin	38.481878, -81.361603	Chimney Mastic	5 SF	Assumed	J. Frazier AI008690	3/20/2017	Mikaela Batta	
K-174	1964 Jordan Creek Rd., Elkview	38.482234, -81.390133							
K-199	311 Brown Street, Clendenin	38.477640, -81.369491	Old Wire (back top of pile)	25 LF	Assumed	J. Frazier AI008690	4/21/2017	Samantha Card	

WEST VIRGINIA



RECEIVED
MAY 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (3LC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 4/28/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: Check No:
Postmark Date: Paid By:
Notification No: Amount: \$

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Group 6 (Kanawha County) Address: City: Location Within Facility: County: Number of Floors: Age (Yrs): Building Size (Sq. Ft.): Prior Use: Present Use:	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002453 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Jason Frazier WV License #: AI008690 Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Chris Ciappina WV License #: AD003839 Air Monitor: WV License #:	
Schedule: Asbestos Removal: Start Date: 05/01/17 Completion Date: 06/01/17 Demo/Renovation: Start Date: 05/01/17 Completion Date: 06/01/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation: Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.																			
Demolition Ordered by Government Agency: Agency: _____ Title: _____ Name: _____ Date Order to Begin: ___/___/___ Date of Order: ___/___/___ (Copy of order must be attached.)																			
Types of ACM:																			
Asbestos Containing Material To Be Removed:	Cat. I & II Nonfriable ACM Not To Be Removed:																		
Type(s): Please see attached. <table style="width: 100%; border: none;"> <tr> <td style="width: 33%;">Pipes:</td> <td style="width: 33%;">Ln. Ft:</td> <td style="width: 33%;">% Asbestos:</td> </tr> <tr> <td>Area:</td> <td>Sq. Ft:</td> <td>% Asbestos:</td> </tr> <tr> <td>Other:</td> <td>Cu. Ft:</td> <td>% Asbestos:</td> </tr> </table>	Pipes:	Ln. Ft:	% Asbestos:	Area:	Sq. Ft:	% Asbestos:	Other:	Cu. Ft:	% Asbestos:	Type(s): <table style="width: 100%; border: none;"> <tr> <td style="width: 33%;">Pipes:</td> <td style="width: 33%;">Ln. Ft:</td> <td style="width: 33%;">% Asbestos:</td> </tr> <tr> <td>Area:</td> <td>Sq. Ft:</td> <td>% Asbestos:</td> </tr> <tr> <td>Other:</td> <td>Cu. Ft:</td> <td>% Asbestos:</td> </tr> </table>	Pipes:	Ln. Ft:	% Asbestos:	Area:	Sq. Ft:	% Asbestos:	Other:	Cu. Ft:	% Asbestos:
Pipes:	Ln. Ft:	% Asbestos:																	
Area:	Sq. Ft:	% Asbestos:																	
Other:	Cu. Ft:	% Asbestos:																	
Pipes:	Ln. Ft:	% Asbestos:																	
Area:	Sq. Ft:	% Asbestos:																	
Other:	Cu. Ft:	% Asbestos:																	
Description of planned demolition or renovation work and method(s) to be used: Wet methods for demolition and regulated site.																			
Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M): Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.																			
Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder: STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.																			
Waste Transporter: <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Name: Reclaim Company, LLC</td> <td style="width: 50%;">ID #: WV042918 / WH13715</td> </tr> <tr> <td>Address: P.O. Box 2162</td> <td></td> </tr> <tr> <td>City: Fairmont</td> <td>State: WV Zip Code: 26555</td> </tr> <tr> <td>Contact Person: Steve Gabbert</td> <td>Phone: 304-366-7070</td> </tr> </table>		Name: Reclaim Company, LLC	ID #: WV042918 / WH13715	Address: P.O. Box 2162		City: Fairmont	State: WV Zip Code: 26555	Contact Person: Steve Gabbert	Phone: 304-366-7070										
Name: Reclaim Company, LLC	ID #: WV042918 / WH13715																		
Address: P.O. Box 2162																			
City: Fairmont	State: WV Zip Code: 26555																		
Contact Person: Steve Gabbert	Phone: 304-366-7070																		
Waste Disposal Site: <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Name: Meadowfill Landfill</td> <td style="width: 50%;">ID #: SMF-1032</td> </tr> <tr> <td>Address: Rt. 2 Box 68</td> <td></td> </tr> <tr> <td>City: Bridgeport</td> <td>State: WV Zip Code: 26330</td> </tr> <tr> <td>Contact Person: Kelli Sekela</td> <td>Phone: 304-842-2784</td> </tr> </table>		Name: Meadowfill Landfill	ID #: SMF-1032	Address: Rt. 2 Box 68		City: Bridgeport	State: WV Zip Code: 26330	Contact Person: Kelli Sekela	Phone: 304-842-2784										
Name: Meadowfill Landfill	ID #: SMF-1032																		
Address: Rt. 2 Box 68																			
City: Bridgeport	State: WV Zip Code: 26330																		
Contact Person: Kelli Sekela	Phone: 304-842-2784																		
Certification: I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.																			
Signature of Owner/Operator: <u>Angela Mitchell</u> Date: <u>04/28/17</u>																			
Name and Title (Print or Type): <u>Angela Mitchell, Contract Administrator</u>																			



RECLAIM

WVHSEM / FEMA

June 23rd Flood Cleanup Project

Kanawha County, WV - Group 6

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTILE	INSPECTOR	INSPECTION DATE	ANALYST	COMPLETE
K-25	306 Maywood Drive, Clendenin	38.48730, -81.35205	Mastic around roof vent	4 LF	Assumed	J. Sommers AI008854	12/7/2016	Anna Malmberg	X
K-24	110 Maywood Avenue, Clendenin	38.48825, -81.34988	Linoleum	12 SF	Assumed	J. Sommers AI008854	12/7/2016	Anna Malmberg	X
K-20	214 Koontz Avenue, Clendenin	38.489924, -81.34357	Wiring in house	100 LF	Assumed	J. Sommers AI008854	12/7/2016	Scott Minyard	X
K-14	202 Elk Avenue, Elkview	38.48844, -81.35105	Roof vent mastic	2 LF	Assumed	J. Frazier AI008690	4/20/2017	Mikaela Batta	
K-27	5 Pleasant Street, Clendenin	38.48784, -81.35135	Mastic around roof vent	5 LF	Assumed	J. Sommers AI008854	12/7/2016	Anna Malmberg	X
K-80	110 Koontz Avenue, Clendenin		Transite Siding	800 SF	15%	J. Frazier AI008690	12/13/2016	Sarah Talley	X
			Floor Tile	150 SF	Assumed				

WEST VIRGINIA



RECEIVED
MAY 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (3LC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 4/28/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: Check No:
Postmark Date: Paid By:
Notification No: Amount: \$

Type of Notification: Original <input type="checkbox"/> Revision <input checked="" type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Group 14 (Greenbrier) Address: City: County: Location Within Facility: Building Size (Sq. Ft.): Number of Floors: Age (Yrs): Present Use: Prior Use:	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002453 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Please see attached. WV License #: Please see attached. Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Chris Ciappina WV License #: AD003839 Air Monitor: WV License #:	
Schedule: Asbestos Removal: Start Date: 04/03/17 Completion Date: 06/01/17 Demo/Renovation: Start Date: 04/03/17 Completion Date: 06/01/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Title:

Date of Order: ___/___/___

Date Order to Begin: ___/___/___

(Copy of order must be attached.)

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): **Please see attached.**

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.**Waste Transporter:**

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: Date: 04 / 28 / 17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 14

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTILE	INSPECTION DATE	INSPECTOR	ANALYST
G-252	231 HONAKER HOLLOW RD., CALDWELL	37.766931, -80.392479	Black Mastic on Roof	10 SF	Assumed	3/23/2017	K. Tuckwiller AI008994	Samantha Card
G-239	696 TUCKAHOE RD., WHITE SULPHUR SPRINGS	37.790345, -80.290943	NO SUSPECT MATERIALS	N/A	N/A	3/23/2017	K. Tuckwiller AI008994	N/A
G-245	187 GEORGEANNA DR., WHITE SULPHUR SPRINGS	37.915892, -80.209482	NO SUSPECT MATERIALS	N/A	N/A	3/23/2017	K. Tuckwiller AI008994	N/A
G-109	202 WEBB ST., WHITE SULPHUR SPRINGS	37.803603, -80.29755	Mastic on Roof Vent/Chimney	3 SF	Assumed	3/23/2017	K. Tuckwiller AI008994	Taylor B. Metcalf
G-111	219 CRESCENT AVENUE, WHITE SULPHUR SPRINGS	37.797888, -80.300358	Transite Siding	300 SF	Assumed	3/23/2017	K. Tuckwiller AI008994	Samantha Card
G-257	238 4TH STREET, CALDWELL	37.779346, -80.391948	Mastic around Roof vents (under metal roofing)	5 SF	Assumed	3/28/2017	K. Tuckwiller AI008994	Saithya Painkal
G-103	154 2ND STREET, CALDWELL	37.779713, -80.392247	White/Gray Window Glazing	180 LF	2%	3/27/2017	K. Tuckwiller AI008994	149%
G-205	3961 MONROE DRAFT ROAD, CALDWELL	37.755756, -80.403356	Mastic around chimney	4 SF	Assumed	3/27/2017	K. Tuckwiller AI008994	N/A
G-211	650 HEARTS RUN LOOP ROAD, CALDWELL	37.765986, -80.357265	NO SUSPECT MATERIALS	N/A	N/A	3/27/2017	K. Tuckwiller AI008994	N/A
G-112	246 SALISBURY AVENUE, WHITE SULPHUR SPRINGS	37.791595, -80.304954	Brown/White Linoleum	350 SF	25%	3/27/2017	K. Tuckwiller AI008994	Samantha Card
G-171	530 BIG DRAFT ROAD, WHITE SULPHUR SPRINGS	37.799785, -80.301775	Mastic around roof vents	5 SF	Assumed	3/27/2017	K. Tuckwiller AI008994	Shilpa Ladekar
G-178	126 VAN STAVEN LANE, WHITE SULPHUR SPRINGS	37.835262, -80.256981	Roofing Material (Bldg 1)	110 SF	Assumed	3/27/2017	K. Tuckwiller AI008994	Samantha Card
G-179	241 FREELAND AVENUE, WHITE SULPHUR SPRINGS	37.802313, -80.290882	Window Glazing	80 LF	Assumed	3/27/2017	K. Tuckwiller AI008994	Saithya Painkal
G-231	43117 MIDLAND TRAIL, EAST, WHITE SULPHUR SPRINGS	37.798882, -80.279446	Silver Roof Cement	700 SF	2%	3/27/2017	K. Tuckwiller AI008994	Sarah Talley
G-233	208 FREELAND AVENUE, WHITE SULPHUR SPRINGS	37.802245, -80.290287	Mastic on Siding/Roof Vents	10 SF	Assumed	3/27/2017	K. Tuckwiller AI008994	Scott Minyard
G-261	160 MOUNTAINEER LANE, WHITE SULPUR SPRINGS	37.795663, -80.275982	Gray/Black Silver Roof Cement	500 SF	2%	3/28/2017	K. Tuckwiller AI008994	N/A
G-263	228 HOLMES LANE, WHITE SULPHUR SPRINGS	37.794948, -80.296896	Mastic around roof vents	5 SF	Assumed	4/4/2017	K. Tuckwiller AI008994	N/A
G-198	162 1st STREET, CALDWELL	37.779797, -80.393328	Black Roof Tar	500 SF	10%	4/24/2017	K. Tuckwiller AI008994	Megan Rumble
G-169	154 TUNNEL LOOP ROAD, CALDWELL	37.776857, -80.393704	Silver Roof Cement	150 SF	Assumed	4/24/2017	K. Tuckwiller AI008994	Megan Rumble
G-289	43220-A MIDLAND TRAIL, EAST, WHITE SULPHUR SPRINGS	37.797610, -80.278891	Caulking around windows (Bldg 1)	20 LF	Assumed	4/24/2017	K. Tuckwiller AI008994	Megan Rumble
G-107	190 MILL HILL DRIVE, WHITE SULPHUR SPRINGS	37.797545, -80.298423	Mastic on Roof Vents/Siding	10 SF	Assumed	4/24/2017	K. Tuckwiller AI008994	Scott Minyard
G-168	142 TUNNEL LOOP ROAD, CALDWELL	37.776693, -80.393704	Red Floor Tile	190 SF	3%	4/24/2017	K. Tuckwiller AI008994	Scott Minyard
			Transite Siding	1400 SF	Assumed	4/24/2017	K. Tuckwiller AI008994	Mikaela Batta
			Yellow Linoleum	120 SF	25%	4/24/2017	K. Tuckwiller AI008994	Mikaela Batta
			Transite Siding	3600 SF	Assumed	4/24/2017	K. Tuckwiller AI008994	Mikaela Batta

WEST VIRGINIA



RECEIVED
MAY 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (3LC62)
PA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION


Date: 4/28/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Group 5 (Greenbrier) Address: _____ City: _____ County: _____ Location Within Facility: _____ Building Size (Sq. Ft.): _____ Number of Floors: _____ Age (Yrs): _____ Present Use: _____ Prior Use: _____	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002453 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Please see attached. WV License #: Please see attached. Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Chris Ciappina WV License #: AD003839 Air Monitor: WV License #: _____	
Schedule: Asbestos Removal: Start Date: 05/01/17 Completion Date: 06/01/17 Demo/Renovation: Start Date: 05/01/17 Completion Date: 06/01/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation: Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.																			
Demolition Ordered by Government Agency: Agency: _____ Name: _____ Title: _____ Date of Order: ___/___/___ Date Order to Begin: ___/___/___ (Copy of order must be attached.)																			
Types of ACM:																			
Asbestos Containing Material To Be Removed: <hr/> Type(s): Please see attached. <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33%;">Pipes:</td> <td style="width: 33%;">Ln. Ft:</td> <td style="width: 33%;">% Asbestos:</td> </tr> <tr> <td>Area:</td> <td>Sq. Ft:</td> <td>% Asbestos:</td> </tr> <tr> <td>Other:</td> <td>Cu. Ft:</td> <td>% Asbestos:</td> </tr> </table>	Pipes:	Ln. Ft:	% Asbestos:	Area:	Sq. Ft:	% Asbestos:	Other:	Cu. Ft:	% Asbestos:	Cat. I & II Nonfriable ACM Not To Be Removed: <hr/> Type(s): <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33%;">Pipes:</td> <td style="width: 33%;">Ln. Ft:</td> <td style="width: 33%;">% Asbestos:</td> </tr> <tr> <td>Area:</td> <td>Sq. Ft:</td> <td>% Asbestos:</td> </tr> <tr> <td>Other:</td> <td>Cu. Ft:</td> <td>% Asbestos:</td> </tr> </table>	Pipes:	Ln. Ft:	% Asbestos:	Area:	Sq. Ft:	% Asbestos:	Other:	Cu. Ft:	% Asbestos:
Pipes:	Ln. Ft:	% Asbestos:																	
Area:	Sq. Ft:	% Asbestos:																	
Other:	Cu. Ft:	% Asbestos:																	
Pipes:	Ln. Ft:	% Asbestos:																	
Area:	Sq. Ft:	% Asbestos:																	
Other:	Cu. Ft:	% Asbestos:																	
Description of planned demolition or renovation work and method(s) to be used: Wet methods for demolition and regulated site.																			
Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M): Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.																			
Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder: STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.																			
Waste Transporter: <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Name: Reclaim Company, LLC</td> <td style="width: 50%;">ID #: WV042918 / WH13715</td> </tr> <tr> <td>Address: P.O. Box 2162</td> <td></td> </tr> <tr> <td>City: Fairmont</td> <td>State: WV Zip Code: 26555</td> </tr> <tr> <td>Contact Person: Steve Gabbert</td> <td>Phone: 304-366-7070</td> </tr> </table>		Name: Reclaim Company, LLC	ID #: WV042918 / WH13715	Address: P.O. Box 2162		City: Fairmont	State: WV Zip Code: 26555	Contact Person: Steve Gabbert	Phone: 304-366-7070										
Name: Reclaim Company, LLC	ID #: WV042918 / WH13715																		
Address: P.O. Box 2162																			
City: Fairmont	State: WV Zip Code: 26555																		
Contact Person: Steve Gabbert	Phone: 304-366-7070																		
Waste Disposal Site: <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Name: Meadowfill Landfill</td> <td style="width: 50%;">ID #: SMF-1032</td> </tr> <tr> <td>Address: Rt. 2 Box 68</td> <td></td> </tr> <tr> <td>City: Bridgeport</td> <td>State: WV Zip Code: 26330</td> </tr> <tr> <td>Contact Person: Kelli Sekela</td> <td>Phone: 304-842-2784</td> </tr> </table>		Name: Meadowfill Landfill	ID #: SMF-1032	Address: Rt. 2 Box 68		City: Bridgeport	State: WV Zip Code: 26330	Contact Person: Kelli Sekela	Phone: 304-842-2784										
Name: Meadowfill Landfill	ID #: SMF-1032																		
Address: Rt. 2 Box 68																			
City: Bridgeport	State: WV Zip Code: 26330																		
Contact Person: Kelli Sekela	Phone: 304-842-2784																		
Certification: I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.																			
Signature of Owner/Operator: <u></u> Date: <u>04</u> <u>28</u> <u>17</u>																			
Name and Title (Print or Type): <u>Angela Mitchell, Contract Administrator</u>																			



**WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 5**

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSHOTILE	INSPECTION DATE	INSPECTOR	ANALYST	COMPLETE
G-22	1052 Anjean Road, Rupert	37.97223, 80.67572	Door Caulking	40 LF	Assumed	12/5/2016	J. Sommers AI008854	Ritika Seal	X
G-23	119 Feamster Road, Rupert	37.95822, 80.68323	Black Tar (under shingles)	1500 SF	5%	12/5/2016	J. Sommers AI008854	Sarah Talley	X
			Black Tar (around chimney)	5 LF	Assumed				X
G-24	189 Front Street, Rupert	37.96453, 80.69833	Linoleum	110 SF	Assumed	12/5/2016	J. Sommers AI008854	Scott Maynard	X
G-5	4878 Midland Trail W., Charmco	37.780323, 80.384774	Vinyl Floor Tile	32 SF	2%	12/5/2016	J. Sommers AI008854	Ritika Seal	X
			12"x12" Floor Tile	32 SF	Assumed				X
G-16	511 Riverside Drive, Rainelle	37.98970, 80.74742	Window Glazing	48 LF	2%	12/6/2016	J. Sommers AI008854	Candace Burrus	X
			Mastic on Flashing	10 LF	Assumed				X
G-15	121 Riverside Drive, Rainelle	37.995107, 80.749226	White Floor Tile	120 SF	2%	12/6/2016	J. Sommers AI008854	Candace Burrus	X
			White Linoleum	40 SF	Assumed				X
G-56	6972 Midland Trail W., Charmco	37.965185, -80.698525	Transite Siding	1400 SF	Assumed	4/24/2017	K. Tuckwiller AI008994	Sarah Talley	
G-57	6834 Midland Trail W., Hines	37.98448, -80.72123	Black Mastic on house & chimney	25 LF	Assumed	12/15/2016	J. Sommers AI008854	Megan Rumble	X
G-70	141 Front St., Rupert	37.964032, -80.697243	Window Glazing	48 LF	Assumed	12/15/2016	J. Sommers AI008854	Samantha Card	X

WEST VIRGINIA



RECEIVED
MAY 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 4/28/17

Operator Project No: 018-17

OFFICE USE ONLY

Date Rec'd: Check No:
Postmark Date: Paid By:
Notification No: Amount: \$

Type of Notification: Original <input type="checkbox"/> Revision <input checked="" type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Division of Highways Address: 1-79 & Meadowbrook Parkway City: Clarksburg State: WV Zip Code: 26302 Contact Person: Bruce Dunlap Phone: (304) 744-1401	
Facility Description: Name: Vacant Structure Address: 302 Nuzum Place City: Fairmont County: Marion Location Within Facility: Throughout Building Size (Sq. Ft.): 1,650 SF Number of Floors: 3 Age (Yrs): 60+ Present Use: Vacant Structure Prior Use: Residential	
Asbestos Contractor: Name: Reclaim Company, LLC. Asbestos Contractor License #: AC02453 Address: PO Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: (304) 366-7070	
Other Contractor: Name: Reclaim Company, LLC. Contractor's License #: WV042918 Address: PO Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: (304) 366-7070	
Building Inspection: Inspection Date: 3/20/17 Asbestos Inspection By: Christopher Ciappina WV License #: AI008814 Lab: CEI Labs Analysis By: Ritika Seal Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Christopher Ciappina WV License #: AD003839 Air Monitor: WV License #:	
Schedule: Asbestos Removal: Start Date: 4/24/17 Completion Date: 4/28/17 (Completed) Demo/Renovation: Start Date: 4/24/17 Completion Date: 4/28/17 (Completed) Project Work Hours: 7:00 AM to 5:30 PM Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): See Attached Sheet

Type(s):

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet Methods for demolition and regulated Site

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK, Identify the ACM, Develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC.

ID #: WV042918/WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: (304) 366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt.2 Box 68

City: Bridgeport

State: WV


Zip Code: 26330

Contact Person: Kelli Sekela

Phone: (304) 842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 04 / 28 / 17

Name and Title (Print or Type): Christopher Ciappina/Environmental Program Manager



ADDRESS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTILE	INSPECTION DATE	INSPECTOR	ANALYST
302 Nuzum Place	Linoleum (Bathroom)	15 SF	25%	3/20/2017	C. Ciappina AI008814	Ritika Seal
	9" x 9" Beige Floor Tile	117 SF	5%			

P.O. Box 2162 • FAIRMONT, WV 26555



1000



19103

U.S. POSTAGE
PAID
FAIRMONT, WV
26554
MAY 02 17
AMOUNT
\$1.61
R2305K136166-05

**Attention: Asbestos Coordinator(3WC32)
U.S. Environmental Protection Agency
Region III
1650 Arch Street
Philadelphia, PA 19103-2029**

